

Maintenance and Care Instruction

Maintenance:

- No watering, trimming, or touching required.
- Occasionally, gently blow using a feather duster to remove dust from the moss.

Care

Instructions:

- For indoor use only.
- Store in a dry environment with temperatures between 60-85°F.
- Avoid crushing or compression.
- Protect from direct sunlight and strong indirect sunlight, use UV controlled windows for indoor strong indirect sunlight.
- Keep humidity levels between 40% and 80%.
- Maintain a minimum distance of 48" between the artwork and heat-emitting lights.

Important Notes:

- Avoid touching dry or rigid moss, as it may disintegrate.
- Assess and balance humidity levels (40%-80%) for optimal moss condition.
- Once humidity levels normalize, the moss will regain its soft and pliable state.
- For optimal lighting, use LED lights positioned 24" away, employ wash lights for color longevity, minimize continuous usage, and select light temperatures above 3500K for vibrant visuals.