

Maintenance and Care Instruction

Maintenance:

- No watering, trimming, or touching required.
- Occasionally, gently blow using a feather duster to remove dust from the moss.

Care

Instructions:

- For indoor use only.
- Store in a dry environment with temperatures between 60-85°F.
- Avoid crushing or compression.
- Protect from direct sunlight and strong indirect sunlight, use UV controlled windows for indoor strong indirect sunlight.
- Keep humidity levels between 40% and 80%.
- Maintain a minimum distance of 48" between the artwork and heat-emitting lights.

Important Notes:

- Avoid touching dry or rigid moss, as it may disintegrate.
- Assess and balance humidity levels (40%-80%) for optimal moss condition.
- Once humidity levels normalize, the moss will regain its soft and pliable state.
- For optimal lighting, use LED lights positioned 24" away, employ wash lights for color longevity, minimize continuous usage, and select light temperatures above 3500K for vibrant visuals. Please check grammar and style.